Koroseal®

3875 Embassy Parkway Fairlawn, OH 44333

855.753.5474 koroseal.com



| | | US UNITS | METRIC UNITS |
|---|--|--|------------------------|
| Total Weight | | 20.0 oz. PLY 13.3 oz. PSY | 620 g PLM 451 g PSM |
| Roll Width | | 52" – 54" | 132 cm - 137 cm |
| Backing | | Woven | |
| Tensile (Minimum) | | $50 \text{ x} 55 \text{ lb}_{f}$ | 222 x 245 N |
| Tear (Minimum) | | 25 x 25 lb _f | 111 x 111 N |
| Federal Spec. | | CCC-W-408D, Type II | |
| WA Spec. | | WA-101, Type II | |
| ASTM F-793 | | Category V, Type II | |
| Fire Testing | | NFPA 101 [®] Life Safety Code [®] NFPA 255 (ASTM E-84, CAN S102M)) Tunnel Test ¹ Class A Rating Flame Spread - 10 Smoke Developed - 5 NFPA 286 Corner Burn Test ² | |
| CE Certification | | Meets requirements for Flame Spread, Smoke Developed and Flashover EU classification in accordance with EN 15102:2007 + A1:2011 | |
| Indoor Air Quality | | California 01350 – Meets emission requirements for schools and offices | |
| Repeat | Vertical Horizontal Nominal Pattern Width Match Information | N/A N/A 51" Reverse Hang, Random M | Match |
| 1 When applied to GRC board with A-848-B adhesive | | 2 When applied to 5/8" Type-X-Gypsum board with A-848-B adhesive | |

Available in 12 Colorways

| S322-10 Fountain | S322-57 Terrace |
|-------------------|----------------------|
| S322-12 Portico | S322-60 Citadel |
| *S322-42 Chamber | S322-65 Acid Stained |
| S322-48 Monument | S322-80 Plinth |
| S322-50 Raw | S322-90 Underpass |
| S322-55 Brutalist | S322-92 Bunker |

* These decorative metallic wallcoverings should only be cleaned with mild ingredients such as soap, detergent and water. Stronger, more alkaline household cleaners have the potential to damage the surface of the material along with excessive scrubbing.

